

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
TEX
15-SANTN,
SF-

Mission San Jose Y San Miguel De Aguayo, Chapel
6539 San Jose Road
San Antonio -
Bexar County
Texas

HABS No. TX-333 B

Jet Lowe, photographer Summer, 1983

- TX-333 B-1 GENERAL VIEW OF CHAPEL (smaller than church; to right of church).
NOTE SERRATED PARAPET AND THE FAMOUS "RDSE WINDOW" IN CENTER. ALSO
NOTE BUTTRESSES. SOUTH SIDE.
- TX-333 B-2 "RDSE WINDDW", SOUTH SIDE OF CHAPEL
- TX-333 B-3 ENTRANCE DOORWAY, EAST SIDE. DOUBLE DDDRS NOT ORIGINAL
- TX-333 B-4 INTERIOR OF CHAPEL, LOOKING WEST. NDTE DDMED CEILINGS.
- TX-333 B-5 DOORWAY WITH SHELL-SCALLOPED ARCHED OPENING; LEADS TO CHURCH
FROM NDRTH WALL OF CHAPEL

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

ADDENDUM TO:

HABS TX-333-B

MISSION SAN JOSE Y SAN MIGUEL DE AGUAYO, CHAPEL

(San Jose Mission, Chapel)

San Antonio Missions National Historical Park

6539 San Jose Road

San Antonio

Bexar County

Texas

Photographs HABS TX-333-B-1 through HABS TX-333-B-5 were previously transmitted to Library of Congress

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Jet Lowe, photographer, 1983

TX-333-B-6

GENERAL VIEW OF CHAPEL (smaller than church; to right of church). NOTE SERRATED PARAPET AND THE FAMOUS "ROSE WINDOW" IN CENTER. ALSO NOTE BUTTRESSES. SOUTH SIDE. Duplicate color view of HABS TX-333-B-1